

GVC3210 Firmware Release Note

Table of Content

FIRMWARE VERSION 1.0.1.21	2
PRODUCT NAME.....	2
DATE	2
CHANGES SINCE FIRMWARE VERSION 1.0.1.20.....	2
<i>ENHANCEMENT</i>	2
<i>BUG FIX</i>	2
FIRMWARE VERSION 1.0.1.20	3
PRODUCT NAME.....	3
DATE	3
CHANGES SINCE FIRMWARE VERSION 1.0.1.18.....	3
<i>ENHANCEMENT</i>	3
<i>BUG FIX</i>	3

FIRMWARE VERSION 1.0.1.21

PRODUCT NAME

GVC3210

DATE

5/11/2018

CHANGES SINCE FIRMWARE VERSION 1.0.1.20

ENHANCEMENT

BUG FIX

- Removed the new version tips dialog for GVC3210 remote control.
- Added remote control reconnection mechanism instructions after GVC3210 remote control upgrades successfully. This behavior will avoid the remote control version numbers missing issue in GVC3210.

FIRMWARE VERSION 1.0.1.20

PRODUCT NAME

GVC3210

DATE

3/9/2018

CHANGES SINCE FIRMWARE VERSION 1.0.1.18

ENHANCEMENT

BUG FIX

- Fixed the device's default ring tone muted issue after factory reset the device.
- Fixed EPTZ does not work issue when users access the Camera menu.
- Fixed GVC3210 system UI crash issue when users press remote control on User Guide application after the device factory reset and boots up.
- Fixed GVC3210 video image frozen issue when the device receives REINVITE which was different from the initial INVITE.
- Fixed GVC3210's demo video image frozen issue when the device is receiving demo video image and then receives REINVITE.
- Fixed GVC3210 cannot display demo video image issue when other GVC device starts presentation after the GVC3210 starting/closing presentation.